


Schematic Flow Diagram – 2 Position Sample Injector

10 Port Internal Volume Sample Injector P Type Valves, All Series

All Valco valves must be properly supported during tightening or loosening of fittings. This is best effected by the use of one wrench to support the valve body while another wrench tightens or loosens the nut.

Never use the valve shaft as a lever while tightening or loosening nuts.





Europe, Asia, and Africa contact:



TN-309 10/00